

## **Lufttüchtigkeitsanweisung/ Sicherheitsmitteilung**

**Nummer:** 01/09+014/2002

**Datum:** 26.1.02

**Betreff Flugzeug Typ:** FK9 Mk3 + FK14

**Detail:**  
Höhenrudermassenausgleich + Trimmruder

**Auszuführen:**  
Vor nächstem Flug

**Betreff Baunummern:**  
FK9: #090 – 174  
FK14: #001-024

### **Gegenstand:**

#### **1.Scharniere Flettnerruder**

Die Scharnierstifte sind auf sicheren Sitz zu überprüfen. Danach die Enden mit Sicherungslack gut benetzen!

#### **2.Befestigung der HR-Massenausgleiche:**

Die Verschraubungen der Ausgleichsmassen sollen nacheinander entfernt und mit Zugabe von Zweikomponenten-Kleber (UHU Plus) wieder eingesetzt werden.

## **Airworthiness instruction/ safety instruction**

**No.:** 01/09+014/2002

**date:** january 26th 2002

**relating aircraft type:** FK9 Mk3 + FK14

**detail:**  
elevators-counterweights + trim tab

**to be proceed:**  
before next flight

**relating serial no.:**  
FK9: #090 – 174  
FK14: #001-024

### **subject:**


#### **1.trim-tab hinges:**

the hinge axles has to be controlled for proper positioning. Thereafter they have to be secured  
With a drop of colour on their ends!



#### **2.Installation of elevator mass ballance:**

The screws of the counterweights have to be removed and screwed in by adding of two component glue as UHU Plus or similar.



---

**Information erhalten, Unterschrift Flugzeughalter  
Information received, signature aircraft owner  
Please sign and fax back to: 00(49) 6232 – 720 78!**